


**ALL CABLE SCREENS MUST  
BE TERMINATED TO  
THE CABLE GLANDS**

# RFM 1



RFM ENCLOSURE BONDED TO EARTH (SHIP'S HULL)  
VIA min 4mm<sup>2</sup> csa CABLE OR 2 x 1.5mm<sup>2</sup> csa CABLES

**NOTE 1 :** ALL NETWORK CABLES ARE TO BE 4 CORE (2 X TWISTED PAIR) WITH OVERALL BRAIDED SCREEN

**NOTE 2 :** ALL CABLE SCREENS MUST BE CORRECTLY TERMINATED TO CABLE GLANDS

**NOTE 3 :** ALL CABLES (NETWORK AND SENSOR) MUST USE THE DESIGNATED CABLE GLAND ENTRY POINT

**ALL UNUSED CABLE GLANDS  
MUST BE FITTED WITH A  
BLANKING PLUG**

SCALE  
NTS  
FINISH

MATERIAL AND SPECIFICATION

ALL DIMENSIONS ARE IN MILLIMETERS  
UNLESS OTHERWISE STATED  
TOLERANCES UNLESS OTHERWISE STATED  
+/- 0.1  
ANG +/-2

ISSUE	A
DATE	03-10-19
TCR	
DRAWN	SAL
CHECKED	MVJ



**INSTRUMENTATION LTD**

PART OF THE **scanjet** GROUP

TITLE  
RFM1 ENCLOSURE  
AND WIRING DRAWING

Datasheet DAT30

DRAWING No

S-001487-RFM-GA

SALES DRAWING ONLY

SHT I  
OF I

A4

